



O: 604 593 8275 F: 604 593 8276  
 WWW.BCHAZMATINSPECTIONS.CA  
 INFO@BCHAZMATINSPECTIONS.CA  
 #220-19358 96 AVENUE  
 SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.  
 SAMPLES SUBMITTED BY: David Furtado  
 LOCATION: 5495 Skupa Ave., Sechelt  
 DATE ANALYZED: March 05/2020  
 BCHI ID: 22671-1

COAST BC HAZMAT INSPECTIONS INC.

## BULK ASBESTOS RESULTS

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
22671-1-1	1	101 Front left room, East wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22671-1-2	2	102 Laundry room, North wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22671-1-3	3	103 Bathroom, West wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22671-1-4	4	104 Entry, South wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22671-1-5	5	106 Storage room, West wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22671-1-6	6	101 Front left room, Floor, First layer	Vinyl tile	Non fibrous>99%	Not Detected
			Mastic	Non fibrous>99%	Not Detected
22671-1-7	7	101 Front left bedroom, Floor, Second layer	Leveling compound	Non fibrous>99%	Not Detected
			Mastic	Non fibrous>99%	Not Detected
22671-1-8	8	101 Front left room, Floor, Third layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22671-1-9	9	102 Laundry room, Floor, First layer	Vinyl tile	Non fibrous>99%	Not Detected
22671-1-10	10	102 Laundry room, Floor, Second layer	Leveling compound	Non fibrous>99%	Not Detected
			Mastic	Non fibrous>99%	Not Detected



COAST BC HAZMAT INSPECTIONS INC.

## BULK ASBESTOS RESULTS

O: 604 593 8275 F: 604 593 8276  
 WWW.BCHAZMATINSPECTIONS.CA  
 INFO@BCHAZMATINSPECTIONS.CA

#220-19358 96 AVENUE

SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.

SAMPLES SUBMITTED BY: David Furtado

LOCATION: 5495 Skupa Ave., Sechelt

DATE ANALYZED: March 05/2020

BCHI ID: 22671-1

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
22671-1-11	11	102 Laundry room, Floor, Third layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Fiberglass 20% Non fibrous 80%	Not Detected
22671-1-12	12	103 Bathroom, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Fiberglass 20% Non fibrous 80%	Not Detected
22671-1-13	13	103 Bathroom, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22671-1-14	14	104 Entry, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Fiberglass 20% Non fibrous 80%	Not Detected
22671-1-15	15	104 Entry, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22671-1-16	16	105 Kitchen, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Fiberglass 20% Non fibrous 80%	Not Detected
22671-1-17	17	105 Kitchen, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected



COAST BC HAZMAT INSPECTIONS INC.

# BULK ASBESTOS RESULTS

O: 604 593 8275 F: 604 593 8276  
 WWW.BCHAZMATINSPECTIONS.CA  
 INFO@BCHAZMATINSPECTIONS.CA

#220-19358 96 AVENUE

SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.

SAMPLES SUBMITTED BY: David Furtado

LOCATION: 5495 Skupa Ave., Sechelt

DATE ANALYZED: March 05/2020

BCHI ID: 22671-1

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22671-1-18	18	106 Storage room, Floor	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22671-1-19	19	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected
22671-1-20	20	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected
22671-1-21	21	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected

Analytical Method: NIOSH 9002 Analyst: Baraa Habash

Coast BC Hazmat Inspections Inc. participates in the AIHA

bulk asbestos proficiency analytical testing program, participant number 223436