



O: 604 593 8275 F: 604 593 8276
 WWW.BCHAZMATINSPECTIONS.CA
 INFO@BCHAZMATINSPECTIONS.CA

#220-19358 96 AVENUE

SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.

SAMPLES SUBMITTED BY: David Furtado

LOCATION: 5530 Sxwelap Ave., Sechelt

DATE ANALYZED: March 5/2020

BCHI ID: 22673

COAST BC HAZMAT INSPECTIONS INC.

BULK ASBESTOS RESULTS

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
22673-1	1	101 Office, Ceiling	Texture coat	Cellulose 2% Non fibrous 98%	Not Detected
			Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22673-2	2	Room 104, Ceiling	Texture coat	Cellulose 5% Non fibrous 95%	Not Detected
			Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
			Mesh	Fiberglass>99%	Not Detected
22673-3	3	106 Office, Ceiling	Texture coat	Cellulose 5% Non fibrous 95%	Not Detected
			Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
			Mesh	Fiberglass>99%	Not Detected
22673-4	4	101 Office, West wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22673-5	5	Room 104, South wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22673-6	6	Room 105, North wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22673-7	7	106 Office, East wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
			Mesh	Fiberglass>99%	Not Detected
22673-8	8	107 Bathroom, North wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected



COAST BC HAZMAT INSPECTIONS INC.

BULK ASBESTOS RESULTS

O: 604 593 8275 F: 604 593 8276
 WWW.BCHAZMATINSPECTIONS.CA
 INFO@BCHAZMATINSPECTIONS.CA

#220-19358 96 AVENUE

SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.

SAMPLES SUBMITTED BY: David Furtado

LOCATION: 5530 Sxwelap Ave., Sechelt

DATE ANALYZED: March 5/2020

BCHI ID: 22673

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
22673-9	9	108 Bathroom, West wall	Filler compound	Cellulose 2% Non fibrous 98%	Not Detected
22673-10	10	101 Office, Floor	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-11	11	103 Entry, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Fiberglass 30% Non fibrous 70%	Not Detected
22673-12	12	103 Entry, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-13	13	Room 104, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22673-14	14	Room 104, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-15	15	Room 105, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected



COAST BC HAZMAT INSPECTIONS INC.

BULK ASBESTOS RESULTS

O: 604 593 8275 F: 604 593 8276
 WWW.BCHAZMATINSPECTIONS.CA
 INFO@BCHAZMATINSPECTIONS.CA

#220-19358 96 AVENUE

SURREY, BC V4N 4C1

CLIENT ID: Coast BC Hazmat Inspections Inc.

SAMPLES SUBMITTED BY: David Furtado

LOCATION: 5530 Sxwelap Ave., Sechelt

DATE ANALYZED: March 5/2020

BCHI ID: 22673

BCHI SAMPLE ID	CLIENT SAMPLE ID	SAMPLE LOCATION	MATERIAL TYPE	OTHER MATERIAL & AMOUNT	ASBESTOS TYPE & AMOUNT
22673-16	16	Room 105, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-17	17	106 Office, Floor, First layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22673-18	18	106 Office, Floor, Second layer	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-19	19	107 Bathroom, Floor	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Cellulose 30% Non fibrous 70%	Not Detected
22673-20	20	108 Bathroom, Floor	Vinyl sheet, Vinyl top	Non fibrous>99%	Not Detected
			Vinyl sheet, Backing	Non fibrous 70%	Chrysotile 30%
22673-21	21	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected
22673-22	22	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected
22673-23	23	Exterior building, Roof	Roll On	Fiberglass 30% Non fibrous 70%	Not Detected

Analytical Method: NIOSH 9002 Analyst: Baraa Habash

Coast BC Hazmat Inspections Inc. participates in the AIHA
bulk asbestos proficiency analytical testing program, participant number 223436